# AGL Loy Yang



**Document No** EPG030M

**Procedure** AGL Loy Yang Electrical Systems

**Bushfire Mitigation Plan** 

**Revision** 7

Site Loy Yang

#### **Document Approval**

Document Authorisation	Position	Approved Date
Christo van Niekerk	General Manager AGL Loy Yang	See Footer
Responsible Officer		
Steve Welton	e Welton Mine Maintenance Superintendent	
Author		
Michael Allgood	Electrical Coordinator	

#### Stakeholders (Delete if not applicable)

Stakeholder	Position	Consulted Date
Matt Walker	Electrical Coordinator	
Michael Allgood	Electrical Coordinator	

Approved Date: 15/01/2025
Approved By: Christo van Niekerk (A30008754)
Uncontrolled When Printed

Document ID: 12558992 Next Review Date: 12/01/2028 1 of 18

Owner: LYM Electrical Supt.

Release Number: 7



### **Contents**

Release Number: 7

Owner: LYM Electrical Supt.

1.	Objective	3
2.	Plan management particulars	3
3.	Policy	3
4.	Purpose and Structure	4
5.	Prescribed Particulars	5
6.	Responsibilities	8
7.	Preventative Strategies	8
8.	List of Works	9
9.	Investigations	13
	Monitoring, Auditing & Reviewing	
	Plan Access & Inspection	
12.	Site Details	14
13.	Details / Description of assets	14
	Qualifications and Experience Requirements	
	Appendices	



### 1. Objective

The objectives of this bushfire mitigation plan are:

- To implement plans, strategies and policies to reduce as far as practicable the risk of fire initiation and spread from mine overhead electrical assets including lines, pole subs and switches.
- > To comply with the requirements of the Electricity Safety Act and the Electricity Safety (Bushfire Mitigation) Regulations
- > To inform internal and external stakeholders of the strategies and contacts relevant to a fire associated with electrical assets at AGL Loy Yang mine
- To link the existing fire plans and policies together in one document to demonstrate how AGL Loy Yang will respond to a bushfire emergency.

This plan has been specifically created to address those fire risks and strategies associated with overhead electrical assets. For general fire mitigation and emergency response to fires the AGL Loy Yang Emergency Management Plan – HSM0001C, Mine Fire Instructions – HSM001M and Fire Risk Mitigation Plan – P000330 Mine fire risk, Period specific fire readiness TARP Should be consulted.

#### 2. Plan management particulars

AGL Loy Yan Mine is the owner and specified operator of the at-risk lines associated with this Bushfire mitigation Plan.

AGL Loy yang Mine operates under company name AGL Loy Yang Pty Ltd, ACN 077985758, ABN 62077985758.

## 3. Policy

AGL Loy Yang Mine is committed to the implementation of bushfire mitigation strategies that reduce the risk, spread and initiation of fire associated with electrical assets. This will be achieved through a combination of strategies including:

- Periodic 3 year inspections of all at risk lines and assets by an independent assessor and annual internal inspection of all overhead assets
- Comprehensive maintenance plans
- Electric line clearance
- Safe operating practices on days of high fire risk



### 4. Purpose and Structure

Loy Yang Mine has no current exemptions from the Electricity safety (Bushfire Mitigation) Regulations 2023.

This document is a subordinate of HSM001M – Mine Fire Instructions.

This document has been specifically created to address the risks associated with electrical assets at AGL Loy Yang Mine and ensure compliance with the Electricity Safety Act and the Electricity Safety (Bushfire Mitigation) Regulations.

# HSM0001C – Emergency Management Plan

Documents the response in the event of an emergency.

#### **HSM001M - Mine Fire Instructions**

Documents the prevention and preparation for general fire risks.

#### EPG030M - Bushfire Mitigation Plan - Mine Electrical Assets

Sets out specific details and actions taken for the prevention and mitigation of fire risks associated with Mine electrical hazards.

#### **Procedures & Policies**

HSP0001M - Electrical Instructions

EPG025M - Loy Yang Mine Electricity Safety Management Scheme

EPG031M - Annual internal overhead asset inspection procedure

27579178 - Electrical line clearance management plan

EPG024M - HV Reeling and Trailing Cable management procedure

Approved Date: 15/01/2025 Document ID: 12558992
Release Number: 7 Approved By: Christo van Niekerk (A30008754) Next Review Date: 12/01/2028
Owner: LYM Electrical Supt. Uncontrolled When Printed 4 of 18



#### 5. Prescribed Particulars

Release Number: 7

Owner: LYM Electrical Supt.

The following section documents the response or action as appropriate to address the specific requirements of the Electricity Safety (Bushfire Mitigation) Regulations in accordance with regulation 6 Prescribed particulars for bushfire mitigation plans – Specified Operators.

Regulation	Requirement	Reference
6(a)	the name, address, email address and telephone number of the specified operator;	Section 6: Responsibilities
6(b)	the position, address, email address and telephone number of the person who was responsible for the preparation of the plan;	Section 6: Responsibilities
6(c)	the position, address, email address and telephone number of the persons who are responsible for carrying out the plan;	Section 6: Responsibilities
6(d)	the email address (if any) and telephone number of the specified operators control room so that persons can be contacted in an emergency that requires action by the specified operator to mitigate the danger of bushfire;	Section 6: Responsibilities
6(e)	the bushfire mitigation policy of the specified operator to minimise the risk of fire ignition from its at-risk electric lines;	Section 3: Policy
6(f)	the objectives of the plan to achieve the mitigation of fire danger arising from the specified operator's at-risk electric lines;	Section 1: Objective
6(g)	a description, map or plan of the land to which the bushfire mitigation plan applies, identifying the location of the specified operator's at-risk electric lines;	Section 12: Site details. Section 13: Asset description. Section 15: Location plan Drawing No. LV43/07-01/001
6(h)	the preventative strategies and programs to be adopted by the specified operator to minimise the risk of the specified operator's at-risk electric lines starting fires;	Section 7: Preventative Strategies Section 8: List of works
6(i)	a plan for inspection that ensures that all of the specified operator's at-risk lines are inspected at regular intervals of no longer than 37 months;	The distribution system poles, switches and substations at AGL LOY YANG MINE are inspected on a three yearly rolling basis with one third completed every year. All findings are reported to the Electrical

Next Review Date: 12/01/2028 5 of 18



Document ID: 12558992 Next Review Date: 12/01/2028

6 of 18

		•	
		Coordinators, risk ranked, and appropriate actions taken.	
		HSP0001M – Electrical Instructions – Section 6.3.15	
6(j)	Details of the processes and procedures for ensuring that each person who is assigned to carry out the inspections referred to in paragraph (i) has satisfactorily completed a training course approved by energy safe Victoria; and (ii) is competent to carry out such inspections;	Section 14: Qualifications and Experience requirements  HSP0001M – Electrical Instructions – Section 6.3.15	
6(k)	details of the processes and procedures for ensuring that persons (other than persons referred to in paragraph (J)) who carry out or will carry out functions under the plan are competent to do so.	All external contractors are vetted to	
6(I)	the operation and maintenance plans for the specified operator's at-risk electric lines—  (i) in the event of a fire; and  (ii) during a total fire ban day; and  (iii) during a fire danger period;	AGL Loy yang mine has 24 hour 7 days a week coverage by HV operators, in the event of a fire all electrical equipment in the area will be de-energised and all fire damaged equipment will be removed from service. When a fire emergency is declared other combating agencies may become involved and take over the control of the situation.  During periods of high fire danger, Mine fire alerts and total fire ban days switching and operating is restricted to emergency use only.  During a fire danger period any level of high fire danger and above, including days of total fire ban as highlighted by the fire danger rating for West & South Gippsland will restrict the operation and maintenance on at-risk electric lines to emergency use only.  For more information reference HSP0001M – Electrical Instructions – Section 6.3.17 & 6.3.18 HSM0001C Volume 4 – Combating Agencies	
6(m)	the investigations, analysis and methodology to be adopted by the specified operator for the mitigation of	Section 9: Investigations	

Release Number: 7

Owner: LYM Electrical Supt.



fire ignition from its at-risk electric	
lines;	

		I =
6(n)	details of the processes and	The Mine Electrical coordinator is
	procedures by which the specified	responsible for this plan is also the
	operator will—	responsible person for the
	(i) monitor the implementation	implementation of the plan.
	of the bushfire mitigation plan; and	
	(ii) audit the implementation of the plan; and	Section 10: Monitoring, Auditing and Reviewing.
	(iii) identify any deficiencies in the plan	
	or the plan's implementation; and	
	(iv) change the plan and the plan's	
	implementation to rectify any	
	deficiencies identified under	
	subparagraph (iii); and	
	(v) monitor the effectiveness of	
	inspections carried out under the plan;	
	and	
	(vi) audit the effectiveness of the	
	inspections carried out under the plan;	
6(o)	the policy of the specified operator in	In the country area as defined by
	relation to the assistance to be	legislation, as of July 2020 – fire rescue
	provided to fire control authorities in the	Victoria (FRV) will always investigate the
	investigation of fires near the specified	cause of a fire that that they attend.
	operator's at risk electric lines.	Consequently the preservation of
		evidence in the vicinity of the fire is
		critical. Only work that is necessary to
		actually extinguish the fire in the area
		should be conducted and no further hose
		down or clean up be performed until
		approved by the CFA incident controller.
		, ,
		HSM0001C – Emergency Management
		Plan – Volume 3 : Management
		Arrangements - section H : Action with
		respect to statutory & other
		investigations.
		miroonganono.

Release Number: 7

Owner: LYM Electrical Supt.



### 6. Responsibilities

Responsibility	Specified Operator	
Name	AGL Loy Yang Mine	
Address Email Address	Bartons Lane, Traralgon South, Victoria, 3844 loyyang@agl.com.au	
Phone Number	(03) 5173 2000	
Responsibility	Preparation	
Position	Electrical Asset Engineer - Mine	
Address Email Address	AGL Loy Yang Mine, Bartons Lane, Traralgon South, Victoria, 3844 zsteyn2@agl.com.au	
Phone Number	0498252341	
Responsibility	Carrying out of the plan	
Position	Mine Electrical Coordinator	
Address Email Address	AGL Loy Yang Mine, Bartons Lane, Traralgon South, Victoria, 3844 mallgood@agl.com.au	
Phone Number	0409558832	
Responsibility	24/7 Emergency Contact (Electrical Fire Emergency)	
Phone Numbers	Mine Control Centre (03) 51733117 or (03) 51733119	

The contacts identified are in relation to a fire emergency associated with electrical assets. For general fire matters reference should be made to HSM0001C – Emergency Management Plan.

## 7. Preventative Strategies

Release Number: 7

Owner: LYM Electrical Supt.

The preventative strategies adopted by AGL Loy Yang mine to minimise fire risk are:

- All new feeder poles used in the Mine distribution system shall be concrete. Long term replacement of wooden poles shall be scheduled when maintenance requires.
  - HSP0001M Mine Electrical Instructions

Document ID: 12558992

Next Review Date: 12/01/2028



- Management of electrical assets, line clearance, total fire ban days in accordance with AGL Loy Yang mine procedures and policies including:
  - HSP0001M Mine Electrical Instructions
- Management of hot works, firefighting, vehicles, fire detection and reporting and emergency response in accordance with AGL Loy Yang mine procedures including:
  - HSM0001C Emergency Management Plan
  - HSM001M Mine Fire Instructions
  - P000330 Mine fire risk, Period specific fire readiness TARP

#### 8. List of Works

The following works are undertaken as part of minimising the risk of fire associated with electrical assets:

Activity	Details	Due Date
Overhead Line inspections (External audit)	A thorough inspection of a third of the system is completed each year; this inspection checks the condition of poles, insulators, crossarms, switches, substations, and all other associated equipment. The methods of inspection include visual using binoculars, camera and drone footage as well as conducting thermography and pole strength measurements (woodscan) for wooden poles.	Prior to the start of fire season each year.
	These inspections will be conducted using the external inspector's Asset Inspection Manual (AIM) and be conducted by a qualified overhead lines inspector.	
	A visual inspection is also conducted on the remaining system feeders each year.	
	The inspector will provide a report prioritising any defects. These defects are to be added to the Overhead asset inspection – Maintenance progress sheet.	
Overhead Line inspection (Internal audit)	Full system visual inspection is completed each year by internal personnel. This inspection checks for line clearance as well	Prior to the start of fire season each year.

Next Review Date: 12/01/2028 9 of 18



	as condition of poles, insulators, conductors, crossarms, switches, substations, and all other associated equipment.  The method of visual inspection includes the use of binoculars and camera.  This inspection will be undertaken by the Electrical Co-Ordinator  Any defects identified are to be risk ranked and added to the Overhead asset inspectionmaintenance progress sheet.	
Overhead asset inspection – Maintenance progress sheet remediation works.	Suitably qualified external contractor linesmen and A grade electricians to complete remedial works as required.	Prior to start of fire season each year or as soon as reasonably practicable taking into consideration the AGL Loy Yang Maintenance Priority Setting Matrix.
Overhead Line clearance inspections (External audit)	The entire overhead line network is audited each year by an external Arboriculture inspector with a report provided.	Prior to the start of fire season each year.
Tree trimming and works as recommended by the external audit report	External tree contractors are engaged to conduct any required works detailed by the external arboricultural report. This work will be undertaken by a qualified arborist.	Prior to the start of fire season each year.
Weed spraying	External contractor to spray any weeds within power distribution centre compounds, around portable power distribution centres and 22kV poles which have switches or substations attached.	Prior to the start of fire season each year.

Document ID: 12558992 Next Review Date: 12/01/2028 10 of 18

Release Number: 7 Owner: LYM Electrical Supt.



There are additional works which are completed as part of the general fire mitigation strategies such as slashing and site clean-up, the details of these activities can be found in HSM001M – Mine Fire Instructions.

All defects identified during the above inspections will be risked ranked as P1 (emergency work) to P5 (outage work) priority as per the AGL Loy Yang Maintenance priority setting matrix. This priority will determine the timeframes for scheduling of repairs where P1 work is to be completed within 24 hours, P2 work within 2 weeks, P3 and 4 as soon as reasonably practicable beyond the 2 week period and P5 work when time allows, usually in an outage. A priority of High corresponds to a P1, Medium to P2 or P3 and low to P4 or P5. This priority setting matrix applies to all results of inspections including full inspections, visual inspections and thermographic inspections.

See the following maintenance progress sheet which was updated from the 2023 overhead asset inspection report. It shows the maintenance defect priorities and notes repair completions. Limited life wooden poles are noted as limited life and reinspected annually until unserviceable and replacement is necessary.

Approved Date: 15/01/2025
Approved By: Christo van Niekerk (A30008754)
Uncontrolled When Printed

Document ID: 12558992 Next Review Date: 12/01/2028 11 of 18

Release Number: 7
Owner: LYM Electrical Supt.



Document ID: 12558992 Next Review Date: 12/01/2028

12 of 18

eport	1	HV Ref Ta	Overhead asset inspection	report 202	.5	1
Year	Pole ID	#	Outstanding issue	Priority	Status	Predicted Repair Da
2022	LY 12000023	34	Feeder 12 Limited Life wooden pole/ replace pole	Medium	Complete 6/2/2024	I
2021	LY 12000034	J.	Concrete pole damaged 1.2 m above ground	None	Monitor	
2023	LY 12000037 Spare S/Sw2	27	Broken earth at switch handle, unused ABS	None	Complete 8/2/2024	
2023	LY 12000037 Spare S/Sw2 LY12000054	27 23	L/A lead off, unused ABS chipped insulator blue phase	None Low	Unused switch Complete 6/2/2024	
2023	LY 12000070	- 25	Slack stay wire	Low	Complete 8/12/2023	
2023	LY 12000066		2x Slack stay wires	Low	Complete 8/12/2023	
2023	LY 12000079 12-3 LY 12000097 12-5		Broken earth tie Slack stay wire	Low Low	Complete 6/2/2024 Complete 6/2/2024	
2023	LY 12000097 12-5		Birds nest on gas switch	Medium	Complete 6/2/2024	
2023	LY 12000047		Slack stay wire nearly touching earth	Medium	Complete 6/2/2024	
2023	LY 12000080 LY 12013001 Art Monitoring sub	3	Broken earth wire rubbing on slack stay 8/12 Rusty sub bottom	Medium None	Complete 6/2/2024  Monitor	
2023	LY 12000057	1	slack stay wire	None	Complete 8/12/2023	
2023	LY15015008 PDC24 S/Sw	17	Bushing cover fallen off	Medium	Complete 7/2/2024	ı
2023	E1130130001 DC24 3/3W	17	Feeder 16	IVICUIUIII	Complete 1/2/2024	
2022	LY 16006002, S/Stn 13 S/Sw	37	Limited Life wooden pole	Low	Re-inspect in 12 months	
2022	LY16000028 LY 16000011 FDR16 EMS STN Sw	unsure 20	Limited Life wooden pole/ replace pole  Possible weeping on transformer bushings	Low Medium	Monitor  Could not detect leak, slight rust, Monitor	
2021	LY 1600007		Pole has 4 degree lean	Negligable	Monitor	
2023	LY 16000030		pole missing concrete and reo rust, Limited life pole		Re-inspect in 12 months	
2023	LY 16028010 RTL sub	1	HV bridging insulator small chip  Feeder 19	Low	Monitor	
2022	LY 1900022 S/STN 42		Limited Life wooden pole	Low	Re-inspect in 12 months	
2023	LY 19034003 sub 49	24	slack stay wire and rust at eye bolt	Low	Complete 7/2/2024	
2023	LY 1900022 S/STN 42 LY 19000017 S/STN 55	21 26	LV bushing cover missing  HV bushing covers deteriorated	Low Medium	Cover not required.  Waiting for access, inspected and still serviceable	
2023	E1 1200001/ 3/31N 33	20	Feeder 21	ivieuiuiii	vvaring for access, hispected and still serviceable	
2023	LY 21000023 FS PS3 sub	50	LV bushing covers removed	Low	Complete 8/2/2024	
2023	LY 21000021 Sub 70	4	LV bushing cover missing Feeder 22	Low	Complete 8/2/2024	
2023	LY 22000036	45	broken conductor strands blue phase	High	Complete 6/12/2023	
2023	LY 22000036	45	Broken HV glass disc blue phase	High	Complete 6/12/2023	
2023	LY 22000064	8	Broken HV tie centre phase	High	Complete 7/2/2024	
2023	LY 22000062	44	Slack stay wire	Low	Complete 8/12/2023	
2023	LY 22000063	9	Slack stay wire	Low	Complete 8/12/2023	
2023	LY 22000071	19	Slack stay wire	Low	Complete 6/12/2023	
2023	LY 22000072		Slack stay wire	Low	Complete 8/12/2023	
2023	LY 22000073	42	Chipped HV insulator	Low	Complete 7/2/2024	
2023	LY 22000076		Slack stay wire	Low	Complete 8/12/2023	
2023	LY22000082	-	Slack stay wire	Low	Complete 8/12/2023	
2023	LY 22000091 LY 22000096		Slack stay wire	Low	Complete 8/12/2023	
2023	LY 22000096		Slack stay wire Missing split pin on connector nut W phase	Medium	Complete 8/12/2023  Complete 7/2/2024	
2023	LY 22090003 Spare S/Sw 3		Conductor to LA disconnected, unused switch	None	Complete 7/2/2024	
2023	LY 22076004		HV bird cover moved	Low	Complete 7/2/2024	
2023	LY 22076007		broken earth strands on pole near L/A	Low	Complete 7/2/2024	
2021	LY 23002005	1	Feeder 23 Bird nest just below crossarm	None	Not there, monitor for return.	
2023	LY 23000010 S/STN 9 S/Sw	18	LV bushing cover missing	Low	Complete 11/1/2024	
2023	LY 23000020 23-3 L801 S/Sw	39	HV cable head has burn marks near L/A	Low	Complete 11/1/2024	
	1		Feeder 25		_	
2023	LY 25000001	25	HV conductor broken strands and loose D clamp, White phase	High	Complete 6/12/2023	
2023	LY 25000004	7	HV strain insulator nut loose	Medium	Complete 6/12/2023	
2022	Ly acousage appear	20	Feeder 26		0 1 0 0 0 0 0 0 0	
2023	LY 26045003 PDC31	30	birds nest on switch Feeder 27	Medium	Complete 8/2/2024	
2023	LY 2701609 Spare S/Sw 6	AGL	Gas switch failure, replacement	Low	Complete 5/12/2023	
2023	LY 27000072		2 x slack stay wires	Low	Complete 8/12/2023	
2023	LY 27000076 LY 27000066	-	Slack stay wire 2x Slack stay wires	Low Low	Complete 8/12/2023 Complete 8/12/2023	
	LY 27000056	41	Connecting bolt missing split pin W phase	Medium	Complete 6/2/2024	
2023	LY 27012001	46	Slack stay wire	None	Monitor	
			Feeder 31			
2023	LY 31000033	20	broken tie centre phase	High	Complete 7/12/2023	
2023	LY 31000033 LY 31069002	29 10	broken tie centre phase HV and LV bushing covers missing	High High	Complete 7/12/2023 Complete 6/12/2023	
2023 2023 2023 2023	LY 31069002 LY 31017005X1	10 35	HV and LV bushing covers missing Pole has termites/ replace earth pole	High Low	Complete 6/12/2023 Complete 7/12/2023	
2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003	10 35 11	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt	High Low Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023	
2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1	10 35	HV and LV bushing covers missing Pole has termites/ replace earth pole	High Low	Complete 6/12/2023 Complete 7/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017002 LY 31000061 LY 31000084	10 35 11 47	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire and rust at eye bolt Slack stay wire Slack stay wire	High Low Low Low Low Low Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000085	10 35 11 47	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire and rust at eye bolt Slack stay wire Slack stay wire Slack stay wire Slack stay wire	High Low Low Low Low Low Low Low Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2023 Complete 8/12/2023 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000085 LY 31000070	10 35 11 47	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire and rust at eye bolt Slack stay wire Slack stay wire Slack stay wire 2x slack stay wire	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2023 Complete 8/12/2023 Complete 8/12/2023 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000070 LY 31000070 LY 31000075 LY 31000095 LY 31000104A	10 35 11 47	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000070 LY 31000095 LY 31000095 LY 31000104A LY 31000106A 31-6	10 35 11 47	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire Slack stay wire Slack stay wire Slack stay wire 2x slack stay wire Slack stay wire Slack stay wire Earth insulation chewed by cattle	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000085 LY 31000070 LY 31000104A LY 31000104A LY 31000106A 31-6 LY 31000106A 31-6	10 35 11 47	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire Ex slack stay wire	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000070 LY 31000095 LY 31000095 LY 31000104A LY 31000106A 31-6	10 35 11 47	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire Slack stay wire Slack stay wire Slack stay wire 2x slack stay wire Slack stay wire Slack stay wire Earth insulation chewed by cattle	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000085 LY 31000070 LY 31000104A LY 31000106A 31-6 LY 31000106A 31-6 LY 31009008 LY 3100008 LY 31009008 LY 31009008 LY 31069008 LY 31106022	10 35 11 47 43	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire Glack Stay wire Glack Stay wire Slack Stay wire Slack Stay wire Slack Stay wire Ghip on insulator Birds nest on gas switch	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	Y 31069002   V 31017005X1   V 31017003   V 31017002   V 31000061   V 31000084   V 31000070   V 31000070   V 31000104A   V 31000106A 31-6   V 31000106A 31-6   V 3100008   V 31000106A 31-6   V 31000036   V 31000036	10 35 11 47 43	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire and rust at eye bolt slack stay wire Carb in sulation chewed by cattle Earth insulation chewed by cattle Slack stay wire Larth insulation chewed by cattle Slack Stay wire Chip on insulator Birds nest on gas switch  Feeder 32 HV Strain insulator pin and bolt fallen out	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2024 Complete 6/2/2024	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000070 LY 31000070 LY 31000106A LY 31000036 LY 3106022 LY 32000036 LY 32029004 5/Stn L701 5/Sw	10 35 11 47 43 16	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire Ex slack stay wire Earth insulation chewed by cattle Slack Stay wire Earth insulation chewed by cattle Slack Stay wire Slack Stay wire Earth insulation chewed by cattle Slack Stay wire Exit insulation chewed by cattle Slack Stay wire Feeder 32 HV Strain insulator pin and bolt fallen out Birds nest on gas switch	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2024 Complete 6/2/2024 Complete 6/2/2024 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	Y 31069002   V 31017005X1   V 31017003   V 31017002   V 31000061   V 31000084   V 31000070   V 31000070   V 31000104A   V 31000106A 31-6   V 31000106A 31-6   V 3100008   V 31000106A 31-6   V 31000036   V 31000036	10 35 11 47 43	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire and rust at eye bolt slack stay wire Carb in sulation chewed by cattle Earth insulation chewed by cattle Slack stay wire Larth insulation chewed by cattle Slack Stay wire Chip on insulator Birds nest on gas switch  Feeder 32 HV Strain insulator pin and bolt fallen out	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2024 Complete 6/2/2024	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000085 LY 31000070 LY 31000104A LY 31000106A 31-6 LY 31009008 LY 31106022 LY 320200036 LY 32020004 S/Stn L701 S/Sw LY 32029004 S/Stn L701 S/Sw	10 35 11 47 43 16 32 48 48	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire Sl	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2024 Complete 8/12/2023 Monitor Complete 5/2/2024 Complete 8/12/2023 Complete 8/12/2023 Complete 8/12/2023 Complete 8/12/2023 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000085 LY 31000070 LY 31000106A LY 31000106A 31-6 LY 31009008 LY 31106022 LY 32000036 LY 32000036 LY 32000036 LY 32000036 LY 32000036 LY 32000005	10 35 11 47 43 43 16 32 48 48 12	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire Larth insulation chewed by cattle Slack Stay wire Chip on insulator Birds nest on gas switch HV strain insulator pin and bolt fallen out Birds nest on gas switch HV strain bird damaged Birds nest on gas switch Pole leaning 5 degrees Feeder 34	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2023 Monitor Complete 5/2/2024 Complete 8/12/2023 Monitor	
2023 2023 2023 2023 2023 2023 2023 2023	Y 31069002     Y 31017005X1     Y 31017005X1     Y 31017003     Y 31017002     Y 31017002     Y 31000061     Y 31000084     Y 31000070     Y 31000070     Y 31000104A     Y 31000106A 31-6     Y 3100016A 31-6     Y 31006A 31-6     Y 31069008     Y 31106022     Y 32000036     Y 32029004 S/Stn L701 S/Sw     Y 32041003 PDC 31     Y 32000005     Y 34000010 S/STN 24 S/Sw     Y 34000010 S/STN 24 S/Sw	10 35 11 47 43 43 16 32 48 48 12	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire Sl	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2023 Monitor Complete 8/12/2024 Complete 8/12/2023	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017003 LY 31017002 LY 31000061 LY 31000084 LY 31000085 LY 31000070 LY 31000106A LY 31000106A 31-6 LY 31009008 LY 31106022 LY 32000036 LY 32000036 LY 32000036 LY 32000036 LY 32000036 LY 32000005	10 35 11 47 43 43 16 32 48 48 12	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire Larth insulation chewed by cattle Slack Stay wire Chip on insulator Birds nest on gas switch HV strain insulator pin and bolt fallen out Birds nest on gas switch HV strain bird damaged Birds nest on gas switch Pole leaning 5 degrees Feeder 34	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2024 Complete 8/12/2024 Complete 8/2/2024 Complete 8/2/2024 Complete 8/12/2023 Monitor Complete 6/2/2024 Complete 8/12/2023 Complete 6/2/2024	
2023 2023 2023 2023 2023 2023 2023 2023	LY 31069002 LY 31017005X1 LY 31017003 LY 31017003 LY 31017002 LY 31000061 LY 31000061 LY 31000084 LY 31000070 LY 31000070 LY 3100016A LY 3100016A LY 3100016A 31-6 LY 3100016A 31-6 LY 3100016A LY 310016A LY 310016A LY 3105008 LY 31106022 LY 3202004 S/Stn L701 S/Sw LY 32029004 S/Stn L701 S/Sw LY 32029004 S/Stn L701 S/Sw LY 32020003 LY 32000036 LY 3200005 LY 34000010 LY 34000010 LY 34000010 LY 34000010 LY 34000010 LY 34000010	10 35 11 47 43 43 16 32 48 48 12	HV and LV bushing covers missing Pole has termites/ replace earth pole slack stay wire and rust at eye bolt slack stay wire Earth insulation chewed by cattle Slack Stay wire Slack Stay wire Earth insulation chewed by cattle Slack Stay wire Slack Stay wire Earth insulation chewed by cattle Slack Stay wire Slack Stay wire Earth insulation chewed by cattle Slack Stay wire Slack Stay wire Slack Stay wire Earth insulation chewed by cattle Slack Stay wire	High Low	Complete 6/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 7/12/2023 Complete 8/12/2023 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2024 Complete 8/12/2023 Monitor Complete 8/12/2024 Complete 8/12/2023	

Release Number: 7

Owner: LYM Electrical Supt.



### 9. Investigations

All fires initiated by electrical apparatus or all events that have the potential to initiate fires at AGL Loy Yang Mine will be investigated to minimise and eliminate the risks associated with bushfire. This includes HV line failures, permit issues resulting in incorrect switching and any other HSE events that have the potential to initiate a fire.

All investigations must be recorded in the myHSE incident reporting system. The level of investigation (i.e. Basic, 5 Whys or ICAM) will be automatically determined by the risk ranking.

The AGL Fully Integrated Risk Matrix (FIRM) must be utilised to determine the risk ranking associated with all events entered into the myHSE system.

The Investigation Lead will be assigned by the Event Manager. The Investigation Lead must commence the investigation within 2 calendar days of receiving the myHSE workflow.

Wherever practicable, the investigation must be completed within 14 calendar days of the workflow being received. Where the investigation is unable to be completed within the allocated time frame the Investigation Leader must seek approval for an extension from the appropriate line manager, prior to the due date.

Once the appropriate approvals have been received, the completed Investigation must be uploaded into myHSE and the Major Root Cause selected prior to the investigation being closed in the myHSE system.

Upon completion of the Investigation the Investigation Lead is responsible for developing a Lessons Learnt. Lessons Learnt must be prepared and distributed as soon as is reasonably practicable upon completion of the investigation.

All fires initiated by Loy Yang Mines at-risk electric lines will be reported to Energy Safe Victoria in accordance with the requirements of the AGL Loy Yang mine Electricity Safety Management Scheme.

Loy Yang Mine has no dangerous or failed at-risk electric lines.

Incident Investigation from the previous year:

- January 24th 2023 Event ID 20109769, Small grass fire occurred below power lines, after fire was extinguished a charred bird was noticed in the vicinity. It is believed this was the cause of the fire. No damage was noted to the power line of feeder switch. Incident reported to Worksafe Victoria. (Worksafe I.D – 219811)
- Only a basic investigation was conducted with the conclusion being the bird had come into contact at the feeder switch causing it to catch fire.

## 10. Monitoring, Auditing & Reviewing

This bushfire mitigation plan is a controlled document and is automatically sent to all relevant parties for review on an annual basis. This review is conducted after the completion of the annual overhead lines inspections and resulting maintenance repairs. If any deficiencies are identified within this plan during these works, the plan will be rectified and sent to the relevant parties for approval.

The Electrical Coordinator conducting Loy Yang Mines Internal Inspection will compare it to the external inspection to gauge its effectiveness. They will also compare previous years maintenance

13 of 18

Next Review Date: 12/01/2028



and fire incidents to measure the effectiveness of the inspections and repair works and review the plan if required.

Monitoring and auditing of the plan, inspections, maintenance strategies are completed during the review and any updates to this document or other relevant procedures is completed at this time.

All year around as well as in declared fire danger periods, Mine fire alerts and total fire ban days the Mine Electrical Coordinator has the responsibility to monitor and implement the appropriate actions as required in this plan.

### 11. Plan Access & Inspection

This bushfire mitigation plan will, on acceptance, be made available via the AGL website <a href="https://www.AGL.com.au">www.AGL.com.au</a> or the AGL Enterprise Library (AEL) via document number: **EPG030M**.

Or a hard copy can be collected from:

AGL Loy Yang Main Gate

**Bartons Lane** 

Traralgon South, Victoria, 3844

24 hours 7 days a week.

#### 12. Site Details

Address:

AGL Loy Yang Mine

**Bartons Lane** 

Traralgon South, Victoria, 3844

## 13. Details / Description of assets

AGL Loy Yang Mines overhead lines surround the mine and overburden dump. All overhead lines are 22Kv with aerial earths and the longest feeder being 11.5 Km in length. See details of each feeder in the following table.

Feeder Number	Number of poles	Number of concrete poles	Number of wooden poles
13	1	1	0
14	9	9	0
15	43	41	2
25	8	8	0
27	150	146	4
31	183	177	6

14 of 18

Document ID: 12558992

Next Review Date: 12/01/2028

Release Number: 7
Owner: LYM Electrical Supt.



11	1	1	0		
21	23	22	1		
22	151	148	3		
23	40	34	6		
26	79	70	9		
32	74	72	2		
12	121	103	18 38 0		
16	78	40			
18	1	1			
19	46	19	27		
34	21	14	7		
35	1	0	1		

### 14. Qualifications and Experience Requirements

Overhead Lines Inspector (External):

- Minimum Certificate II in ESI Asset Inspection and Testing (UET20621)
- 3 years industry experience

Overhead Lines Inspector (Internal):

- Must hold an A Grade Electrician's License
- Must be an Unrestricted High Voltage Operator
- Must be a V Class Electrical Inspector
- Minimum of 3 years Mine Overhead Lines experience

#### Lines Workers:

- Completed training as an electric line worker on high voltage aerial lines
- Hold a current Lineworker license for distribution network (D)
- Completed training for 'Apply ESI safety rules, codes of practice and procedures for work on or near electrical apparatus' and 'Apply access procedures to work on or near electrical network infrastructure'

#### Thermography Inspector:

• Minimum of Level 1 Infrared Thermographer qualification

#### Arboriculture Inspector:

- Minimum Certificate Level III Horticulture (Arboriculture), including "assess" and "identify" modules
- 3 years industry experience

#### Arborist:

- Minimum Certificate Level III Horticulture (Arboriculture), Certificate II in ESI Power line Vegetation Control
- 3 years industry experience

Overhead asset inspection – Maintenance progress sheet.



Rev. 13 Approved 01/09/2021

06/02/2024

Prior to any works commencing and through the Authority to mobilise (Contractor pre-start), the Electrical Coordinator will confirm the qualifications and review previous experience to ensure competency requirements are met.

#### 15. Appendices

Reference Documents:


Release Number: 7

Owner: LYM Electrical Supt.

HSP0001M Loy Yang Mine Electrical Instructions Rev. 12 Approved 18/08/2023 **HSM001M Mine Fire Instructions** Rev. 14 Approved 28/06/2023 HSM0001C Emergency Management Plan - Volume 3: Management Arrangements Rev. 19 Approved 22/12/2022 HSM0001C Emergency Management Plan - Volume 4: Combating Agencies Rev. 2 Approved 21/12/2022 EPG031M Annual Internal overhead asset inspection Procedure Rev. 3 Approved 05/10/2023 P000330 Mine Fire Trigger Action Response Plan (TARP) Rev. 8 Approved 04/08/2023 F000162 AGL Loy Yang Maintenance Notification Priority Setting Matrix Rev. 7 Approved 22/02/2023 22517855 Authority to Mobilise (Contractor Pre-Start) Rev. 2 Approved 08/10/2020 HSP001 Loy Yang HSE Incident, Near Miss and Hazard Management Procedure

Approved Date: 15/01/2025 Document ID: 12558992
Approved By: Christo van Niekerk (A30008754) Next Review Date: 12/01/2028
Uncontrolled When Printed 16 of 18







93								LIKELIHOOD			
,	AGL Loy Yang Maintenance Notification	on Priority Setting Matrix P000162				1 Low	2 Moderate	3 High	4 Very High	5 Almost Certain	
Document No. F000162 Revision 07						PROACTIVE WORK  Preventive Maintenance, Condition Monitoring, Work Statutory Work, Project Work, Unit Outage, Corrective Work					
						Very Rare to have negative consequences if not done by scheduled date	Rare to have negative consequences if not done by scheduled date	Possible to have negative consequences if not done by scheduled date	Almost certain to have negative consequences if not done by scheduled date	Certain to have negative consequences if not done by scheduled date	
						REACTIVE WORK Unscheduled - Corrective Work including Forced Outages					
8							Unscried	Outages			
Conseduen	Safety / People	Environmental	Legal or Regulatory	Generation Plant	Mine Condition	Likelihood of functional failure within  12 months or greater of work request date	Likelihood of functional failure within 6 to 12 months of work request date	Likelihood of functional failure within 3 to 6 months of work request date	Likelihood of functional failure within 14 days of work request date	Functional Failure has occurred OR Likelihood of functional failure within 24 hours of work request date	
5.0	Fatality or Injury resulting in permanent disability Or Serious Injury (LTI)	Significant environmental damage.  Definite prosecution	Inquiry by Regulator with potential loss of contract/s or substantial fines or major litigation	Forced Outage / Unit Trip / Plant failure WILL result in an outage of a Unit, [or delay the Unit Return To Service] > 4 GWhrs Trading Market Alert Day	Catastrophic Critical Tarp No Coal supply. Mandatory offload. No spare machine. No stockpile	P3	P2	P2	Pi	Pí	
4.0	Injury Requires Medical Treatment (MTI)	Significant environmental damage. Risk of prosecutions/large fines	Probable prosecution or investigation and major fine from Regulator	Plant failure MAY result in an outage of a Unit OR WILL significantly reduce capacity or operability. >1 GWhrs <4 GWhrs Within next 48hr period Market Demand / pricing forecast to be significant	TARP 2  No coal supply.  Low Bunker stock.  Stockpile available.  Machines can Repo to coal.	P4	P3	P2	P2	P1	
1.5	First Aid Injury (FAT)	Moderate environmental damage. Potential for EPA action	Possible prosecution or moderate fine or Regulator investigation	Plant failure MAY result in slightly reduce capacity or operability < 1 GWhrs Within next 72hr period Market Demand / pricing forecast to be significant	TARP 1 Impact to coal supply. High bunker continency Machines can Repo to coal	P5	P4	P3	P3	P2	
1.0	No Injury	External incident report. Potential for off- site impact	On the spot fine or non-compliance from Regulator	No existing Generation Loss / Redundant* Plant NOT Available	No Impact to coal supply / Redundant* Plant NOT Available	P5	P4	P4	P4	Р3	
0.5	No Injury	Internal incident report. No off-site impact	Prosecution unlikely	Normal Operation  No Generation Loss / Redundant* Plant Available	Normal Operation  No Impact to coal supply, Redundant plant available	P5	P5	P5	P4	P4	
		PRIORITY	REACTIVE WORK RESPONSE		PROACTIVE WORK RESPONSE			OUTAGE RESPONSE			
REACTIVE WORK Breakdown/Emergency Work			FOR SHARROW DUPY BUILDING		Participation of the Participa						
		Breakdown/Emergency Immediately allocate all necessary resources, prioritise work and do the job, within 24 hours. On Duty Shift Manager authorised to initiate out of hours call in as required.					Outage Soft Spot				
	REACTIVE WORK Break in Work	P2	Break In Work. Immediately plan and prepare to do the job within the current week of the "2 week work schedule" period.						Outage Soft Spot	Forced Outages, Maintenance Outages, Planned Outages & Major Outages work,	
	PROACTIVE WORK High Priority	P3			High Priority Planned Work.  With high priority, work planning/scheduling to commence in week 1 to 2.  The maintenance work to be executed at the next		be executed at the next		mayor outages work, may consist of a combination of Reactive & Proactive Work. The work list will be		
	PROACTIVE WORK Medium Priority	P4			Medium Priority Planned Work. In a timely manner, work planning/scheduling to commence in week 2 to 4.  available opportunity, subject to operational requirements, plant criticality and commenced			conditional on the Response Priority and Due Date of the work.			
	PROACTIVE WORK Low Priority	P5				In a timely manner, work planning/so	y Planned Work. scheduling to commence in week 5 and syond.				

Approved Date: 15/01/2025 Approved By: Christo van Niekerk (A30008754) Uncontrolled When Printed

Release Number: 7 Owner: LYM Electrical Supt. Document ID: 12558992 Next Review Date: 12/01/2028

18 of 18