

# Wind Farm Works Environmental Performance

GE-CATCON regularly reports on environmental performance for the Wind Farm Works in accordance with condition 6 (schedule 4) of the project approval. Presented in the table below is an ongoing summary of environmental performance since works commenced.

Aspect	Performance Target	2017								2018											
		Jun	Jul	Aug	Sep	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	
Visual	Complaints received about visual impacts during construction are minimal	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	Note 1	✓	✓			
Noise	Complaints received about noise during construction are minimal	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Blasting	Complaints received about blasting during construction are minimal	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Air	Complaints received about dust emissions are minimal	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Soil and Water	No construction related soil or water pollution incidents that cause material harm to the environment	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Biodiversity	No more than 0.81ha of Porcupine Grass Sparse Woodland is cleared	✓	✓	✓	✓	✓	✓	✓													
	No more than 6.81 ha of Porcupine Grass Sparse Woodland is cleared								✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
	No more than 0.54 of Mulga/Red Mallee Shrubland is cleared	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
	No construction in mapped Barrier Range Dragon habitat hotspots	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Bird and Bat	Wind turbines erected at least 200m away from raptor nests	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Heritage	No direct disturbance to the five heritage items tabled in the MOD 3 project approval	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Bushfire	No bushfire triggered from construction activities	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Waste	The quantity of waste recycled is greater than the quantity of waste sent to landfill	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Rehabilitation	Areas of disturbed ground exposed for a minimal amount of time	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	Note 2	✓			

**Notes:**

1. Formal complaint received on 11/07/18 in relation to road restoration, visual amenity, enhancement work.
2. Independent Environmental Audit undertaken by MCW Environmental Consulting Pty Limited identified non-conformance with SH3COA3 6 item