

Silverton Wind Farm - Environmental Performance Reporting

GE & AGL provide regular reporting on the environmental performance of the Silverton Wind Farm project on the AGL website in accordance with the reporting arrangements in any plans or programs approved under the conditions of this approval.

This document provides a summary of the environmental monitoring and performance of the Project for the month of **June 2020**.

Environmental Status Aspects Pollution No pollution complaints. complaints Soil, water, No soil or water pollution incidents that cause material harm to the environment. sediment, erosion Birds and Bats Monthly monitoring of bird and bat strikes has been conducted. Trigger levels not exceeded. 1 x Incidental Find, Location WTG01, White-striped free-tail Bat Biodiversity Ongoing actions as per the Operational Biodiversity Adaptive Management Plan, Porcupine Grass Sparse Woodland Recovery Plan, Barrier Range Dragon Management Plan, Goat Management Plan, Vegetation Management Plan No recorded impacts to: Porcupine Grass Sparse Woodland; Mulga/Red Mallee Shrubland; Barrier Range Dragon habitat. Heritage Ongoing actions as per the Heritage Management Plan. No recorded disturbance to heritage items. Fire / Bushfire No bushfires triggered from wind farm operations Waste Waste volumes recorded and appropraitely disposed. Rehabilitation Seed collected and waiting for adequate rainfall. Community The Community Consultative Committee was held in June (remotely) and at the Municiple Chambers in Silverton. The Silverton Community Fund was allocated to two local organisations, the Silverton Village Committee and the Silverton Goal Museum. No major issues were raised except AGL was asked to check on the performance of the new Telstra Small Cell tower as some residents are reporting bad mobile reception. Ongoing environmental reporting completed in accordance with management plans and **Biodiversity reports** Environmental Management Strategy. Annual Vegetation Monitoring Reports Submitted to DPIE in June 2020. Other updates Awaiting information from the Australian Museum in regards to the unidentified carcass found onsite. Noise monitoring loggers were installed in June and are currently being monitored to meet operational

noise compliance requirements.

General Environmental Management Performance